

Messrs.: Valued Customer

Subject: Discontinued of product for J-E2, J-EL2 Series
Machine control DSU board.

March, 2020

Injection Molding Machine Service Group		
Approved by	Checked by	Prepared by
Kanda	Hayashi	Iwasa

JSW The Japan Steel Works, Ltd.
Hiroshima Plant

Discontinued of product for J-E2, J-EL2 Series Machine control DSU board.

Thank you for business with JSW Molding machine.

We would like to take this opportunity to express our sincere appreciation for your business.

We would like to inform you that we have discontinued parts for the DSU boards in the SYSCOM 800(T), SYSCOM 1000(T), that are mounted on the JSW injection molding machines J75Si machine and JE2, JEL2, JTE2 series machine.

This Network board (DSU board) can no longer be repaired. Because more than 20 years have passed since the discontinuation of the production of this series machine, and the stock of the electronic components that make up the controller has been exhausted.

Many electronic components have already been discontinued by component suppliers a few years ago, but "The Japan Steel Works Ltd" and "Oversea JSW Service Branch Office" worked hard to ensure it, but unfortunately cannot be repaired. We have developed new controllers for the J-E2 and JT-E2 series as alternative controllers. However, J-EL2 and J75Si machines are sorry cannot be repaired.

The "SYSCOM 1000 Mark 3" controller has been improved in both specifications and operability compared to the conventional controller, and will satisfy customers not only for repair but also for retrofitting. For more information about the "SYSCOM 1000 Mark 3" controller, please contact JSW service personnel.

If you have any question, please contact our agent or us.

The Japan Steel Works, LTD.

Hiroshima Plant. Injection Molding Machine Service Group.

General Manager.

Koji Kanda



NIPPLA INC.

Head quarter. Service department.

General Manager.

Tatsuya Shikano


